

GVWSA Seasonal Drought/Rainfall









Regional Water Supply Commission Report 20-07

September 16, 2020

Fire Cause – Lightning Storm






View from Mt Tolmie towards the Sooke Hills night of Sunday Aug 16 photo compiled from strikes beginning at 10:30 pm

The Weather





Detection






First view of Mt Healey Fire at 7:14 am Monday

Detection





First view of Rithet fire at 10:18 am Monday (Mt Healey also visible)

Fire Behaviour







Fire behaviour observed

Ground Response







Direct ground suppression with water using tenders, bladders, hose lays at Healey

Ground Response





Trail and heli land spot construction at Rithet – difficult access

Air Response







First response – heli bucketing (CRD and BCWS)

Air Response





First response – heavy helicopters with tank and snorkel (BCWS)

Air Response





Evening amphibious (skimmer) air tanker support

Response






The type of skimmer aircraft used


Location





Fire Perimeter






Mt Healey fire size

Fire Perimeter





Rithet fire size





Mt Healey fire





Mt Healey burned vs. unburned comparison






Mt Healey high and moderate severity burn

Burn Severity Mapping



Burn Severity
Red = high
Orange = moderate
Green = low



Mt Healey






Rithet fire

Burn Severity



Burn Severity
Red = high (none)
Orange = moderate
Green = low

Pink = subbasins



Post fire overview - Healey






Post fire overview - Healey









Regional Water Supply Commission Report 20-07

September 16, 2020